



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

22 Aug
D119-796-151
Job Sheet 180147



Part No: D119-796-151

Job Qty: 1 ea

Part Name: Fwd Crosstube Installation With Step (No Hardware)



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 6/29/18

Job Tracking No:

Due Date: 8/6/18

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG D119-796-151 REV E, IIN-D119-796 REV F IPP REV:A 14.09.09 NEW ISSUE DD VERF:JLM IPP
REV:B 14.11.19 AS PER REV.C DD VERF:JLM IPP REV:C 14.12.09 AS PER REV.PC6 DD VERF:JLM IPP
REV:D 15-02-11 AS PER REV D JLM VERIFIED BY:DD IPP REV:E 17.12.11 REMOVE PICK KIT DD
VERF:DP

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea	8/6/18	8/6/18	0.00	0.00	Start Up Crosstubes-1		AB AUG 30 2018
130	Crosstubes	1 pcs	8/6/18	8/6/18	0.00	0.49	Crosstubes-1		AB AUG 30 2018
140	QC	1 pcs	8/6/18	8/6/18	0.00	0.00	QC5		38
145	DC	1 pcs	8/6/18	8/6/18	0.00	0.00	DC		WPR
150	Packaging	1 pcs	8/6/18	8/6/18	0.00	0.00	Packaging3-1	LG050	AB AUG 30 2018
160	QC21-FG	1 Ea	8/6/18	8/6/18	0.00	0.00	QC21		DAS AUG 30 2018

Part Op 130 - 1- Install step and clamp with the proper position per dwg D119-796-151 ***Torque all clamps to 50 IN-LBS max.***
Descriptions: 140 - ***RE-CHECK TORCQUE ON CLAMP AS PER DWG.***
145 - Photocopy bluefile and create labels as per PPP D119-796-151 chg 005
150 - Identify and pack for shipping as per PPP D119-796-151

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D119-796-141	Fwd Crosstube Installation Without Step (No Hardware)	1 Ea (1 ea)	90-Start up Operation	
D5123-3	Clamp Cushion	4 Ea (4 ea)	90-Start up Operation	
D5149-041	Fwd Step Base Assembly	2 Ea (2 ea)	90-Start up Operation	
MS21920-22	Clamp	4 Ea (4 ea)	90-Start up Operation	

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	D119-796-141 5090244	①	2	0
	D5123-3 F160079	②	361	0
	D5149-041 5054204	②	11	0
	MS21920-22 5045924	④	91	0



Container No: S106704



Part: D119-796-151

Job No: 180147

Serial No/Batch: S106704

Revision: E/F

Inspector:

Exp Date:

Instructions: TC STC SH14-45 - Issue 1, EASA STC SR03504NY 15/01/28, EASA

1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 813 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

ns

be found.

Plex 6/29/18 9:26 AM Dart.lajeunesse.marie

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS <table style="width:100%; border: none;"> <tr> <td style="width:15%;">Skid-tube ☐</td> <td style="width:15%;">Cross tube ☐</td> <td style="width:15%;">Water Jet ☐</td> <td style="width:15%;">Engineering ☐</td> </tr> <tr> <td>Machining ☐</td> <td>Small Fab ☐</td> <td>Prod. Eng. Coord. ☐</td> <td>Quality ☐</td> </tr> <tr> <td>Thermoforming ☐</td> <td>Finishing ☐</td> <td>Rec/Store/Packaging ☐</td> <td>Other ☐</td> </tr> <tr> <td>Large Fab ☐</td> <td>Composite ☐</td> <td>Supplier ☐</td> <td></td> </tr> </table>						Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																						
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																						
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																						
Large Fab ☐	Composite ☐	Supplier ☐																							
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval																		
Description Work Order Deviation				Disposition				Completed By																	
								Lead hand / Supervisor Approval Verification																	
								QC / QA Coordinator Approval																	
Root Cause		FAULT CATEGORY																							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐																				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐																				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐																				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐																				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐																				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐																				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐																				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐																				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐																				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐																				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____																							
Misidentified ☐	Past Due ☐																								